

Drill if necessary to increase threaded M12 holes in cubes (to \emptyset 13mm) Use washers, hex head bolts and screws Close joints with sealant

Assumption: Solid and stable surrounding structures

Attachment bolts according to local conditions

Important: Level the construction accurately both horizontal and vertical

Sign.	Appr. Date			Project	Description	Format	Scale
CS	_	- 12-11-2015		HEB	Detail	A4	1:10
Finlandsvej 12						Drawing no.	
		\triangle			Connection to existing constructions	301301	
		uminium	kontakt@	ajialak	HEB Beam and HEB Cube	Revision	Revision date
Solutions	in glass and al		www.dyfa			_	-